

Vizcaya, Longboat Key, FL

Construction Type:

condominium with aluminum railing systems, windows and door frames.

Challenge:

The salt water environment degraded the existing coatings causing corrosion and color fading and compromised sealant integrity.

Solution:

Complete sealant removal and replacement to restore water-tight building envelope. HVLP painting system applied to all metal railings, doors and frames to stop further corrosion and restore aesthetic appearance of aluminum.



MunyanPainting & Restoration

941-953-2500 www.MunyanPaintingServices.com

2311 Whitfield Park Ave, Sarasota, FL 34243